



February 4, 2011

Mr. Tom Gainer
Oregon Department of Environmental Quality
2020 SW Fourth Avenue, Suite 400
Portland, OR 97201-4987

**Subject: Terminal 4 Slip 1 Upland Facility
Pipeline and Utility Support Rack Footing Excavation Soil Sampling
ECSE No. 2356**

Dear Tom:

This letter provides the Oregon Department of Environmental Quality the Pipeline and Utility Support Rack Footing Excavation Soil Sampling letter for the Terminal 4 Slip 1 Upland Facility. This work was completed in response to observations of discolored soil encountered during excavation of a footing completed as part of a construction project, as initially reported to DEQ on April 1, 2010.

Please call me at (503) 415-6676 if you have any questions.

Sincerely,

A handwritten signature in black ink, appearing to read "Kelly Madalinski". The signature is fluid and cursive, with the first name "Kelly" and last name "Madalinski" clearly distinguishable.

Kelly Madalinski
Environmental Project Manager

c: Kristine Koch, EPA
David Ashton, Port (w/o enclosure)
Suzanne Barthelmess, Port (w/o enclosure)
David Breen, Port (w/o enclosure)
Bill Ford, Lathrop & Gage
Michael Pickering, Ash Creek Associates (w/o enclosure)
Mark Lewis, Formation Environmental (w/o enclosure)
LWP File